



ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124







FIG. 1

BEST AVAILABLE COPY




ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124






ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124



+



ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124








FIG. 3B



ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124





ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124

+




FIG. 3E




FIG. 3F




FIG. 3G

+




FIG. 4



ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124





FIG. 5



ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124





FIG. 6



ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124






FIG. 7




ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124





ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124





ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124





FIG. 10



ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124





ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124





FIG. 12



ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124





FIG. 13



ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124






FIG. 14




ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124








ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124







ROBERT E. KREBS
THELEN REID & PRIEST, LLP
SERIAL NO.: 10/007,204
TRP DOCKET NO.: 034298-000124




FIG. 20




FIG. 21

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☐ FADED TEXT OR DRAWING
- ☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☒ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.